



# GBA Base Can Thread Repair Kit

## FAA L-867 / L-868

### Features

- Guide Ring Assembly for Both L-867 & L-868 Bolt Patterns
- 1/2" Carbide Tipped Drill Bit
- 13mm Reamer
- Drill & Reamer Bushings
- 3/8"-16 Tap with Handle
- Cutting Fluid
- 12" Long 9/16" Ratcheting Box Wrench
- 8" Long 9/16" Combination Wrench
- Wire Brush
- 3/8"-16 x 4" Grade 8 Bolt with Flat Washers & Nut
- 1" Spacer Bushing
- 6 - L-868 Stainless Steel Threaded Inserts
- 6 - L-867 Stainless Steel Threaded Inserts
- Weatherproof Protective Carrying Case



### Ordering Codes

Part Number	Description
BA-TRK67/68	GBA Base Can Thread Repair Kit